MONTANA STATE AVIATION SYSTEM PLAN 1995 UPDATE FIELD INSPECTION FORM

AIRPORT:	BENCHMARK (3U7)	AIRPORT REFERENCE CODE:	B-II (LG)
CITY:	BENCHMARK	APPROACH TYPE:	VISUAL
CONTACT:	U.S FOREST SERVICE	DATE INVENTORIED:	5-20-96
PHONE #:	466-5341	INSPECTED BY:	RSD

	REQUIRED	ACTUAL	ALP	CONFORM
RUNWAY 12/30 INVENTORY				
DISTANCE TO:				
HOLD LINES FROM CENTERLINE:	200'	NONE		NO
PARALLEL TAXIWAY FROM CENTERLINE:	240'	NONE		N/A
AIRCRAFT PARKING FROM CENTERLINE:	250'	200'		NO
RUNWAY WIDTH:	75'	100'		1
RUNWAY LENGTH:	11,230' (1)		6.000'	75%
RUNWAY SAFETY AREA (RSA) WIDTH:	150'	(2)	,,,,,,	NO
RUNWAY OBJECT FREE AREA (OFA) WIDTH:	500'	(3)		NO
PRIMARY / TRANSITION SURFACE PENETRATIONS:	500' W & 7:1	(4)		NO
LONGITUDINAL GRADE - SITE DIST. PROBLEMS:	333 11 31 11	OK		√ · · · ·
OBSTACLE FREE ZONE ANALYSIS:	400' WIDE x 20	-		(3)
PAVEMENT EDGE LIP HEIGHT (MIN AND MAX):	1.5" - 3"	FLUSH		NO
PAVEMENT MARKING TYPE:	BASIC	BASIC		₩
PAVEMENT MARKING CONDITION:	D/ (O/O	POOR (5)		N/A
TAVEMENT WANTED CONDITION.		1 001(0)		14// (
RUNWAY 12 END INVENTORY				
SAFETY AREA (RSA) BEYOND RUNWAY END:	300'	(6)		NO
OBJECT FREE AREA (OFA) BEYOND RUNWAY END:	300'	(7)		NO
APPROACH OBSTRUCTIONS:	20:1	(8)		NO
RUNWAY END ELEVATION:			5,307.1	N/A
RUNWAY 30 END INVENTORY				
SAFETY AREA (RSA) BEYOND RUNWAY END:	300'	(9)		NO
OBJECT FREE AREA (OFA) BEYOND RUNWAY END:	300'	(10)		NO
APPROACH OBSTRUCTIONS:	20:1	(11)		NO NO
RUNWAY END ELEVATION:	20.1	(11)	5,430.4	N/A
RUNWAT END ELEVATION.			5,430.4	IN/A
RUNWAY LIGHTING INVENTORY		NONE		NO
DISTANCE FROM PAVEMENT EDGE:	10'			
MAXIMUM DISTANCE BETWEEN LIGHTS:	200'			
TYPE:				
CONDITION:				
COLOR:	WHITE			
TUDECUOLD 42				
THRESHOLD 12 DISTANCE FROM PAVEMENT EDGE:	101			
	10'			
MAXIMUM DISTANCE BETWEEN LIGHTS:	10'			
COLOR:	RED/GREEN			
THRESHOLD 30				
DISTANCE FROM PAVEMENT EDGE:	10'			
MAXIMUM DISTANCE BETWEEN LIGHTS:	10'			
COLOR:	RED/GREEN	▼		

COMMENTS: (1) RW LENGTH OF 6,800' FOR 75%@60% LOAD, 8,830' FOR 75%@90% LOAD, 10,380' FOR 100%@60% LOAD, AND 11,230' FOR 100% COVERAGE @ 90% MAXIMUM LOAD; FOR SMALL AIRCRAFT - RW LENGTH OF 4,680' FOR 75%, 6,570' FOR 95%, AND 6,590' FOR 100% COVERAGE, ALP ULTIMATE SHOWN AS 6,00 (2) SHOULDERS ARE NOT IN THE 3%-5% RANGE - VERY SHALLOW (3) ROCKS, LOG PIECES, SMALL PINES, SAGE BRUSH & SLASH PILES WITHIN A B-I SIZED OFA. FENCELINES MOSTLY 200' FROM CENTERLINE, BUT SOME AS CLOSE AS 146' FROM CL. OUTSIDE FENCES LARGE PINES IN OFA IN MANY LOCATIONS - PORTION OF ROAD IN OFA; (4) TERRAIN AND PINE TREES PENETRATE PRIMARY SURFACE AND TRANSITIONAL SURFACE ON BOTH SIDES AT MANY LOCATIONS; (5) CENTERLINE STRIPES WERE FAIRLY FADED, BUT END NUMBERS IN GOOD CONDITION - EVIDENCE OF END NUMBER CHANGE FROM 12 TO 14; (6) VERY ROCKY TERRAIN IN OFA WITH UNEVEN TERRAIN STARTING ABOUT 260' FROM RW END 3' PILE OF MATERIAL IN RSA; (7) BRUSH, FENCELINE AND ROAD IN OFA; (SEE FOLLOWING SHEET FOR CONTINUATION OF COMMENTS)

MONTANA STATE AVIATION SYSTEM PLAN 1995 UPDATE FIELD INSPECTION FORM

AIRPORT:	BENCHMARK (3U7)	AIRPORT REFERENCE CODE:	B-II (LG)
CITY:	BENCHMARK	APPROACH TYPE:	VISUAL
OIII.	DENOTIVIAN	ALL ROADH THE.	VIOUAL
CONTACT	U.S FOREST SERVICE	DATE INVENTABLED.	E 20 06
CONTACT:	U.S FUREST SERVICE	DATE INVENTORIED:	5-20-96
PHONE #:	466-5341	INSPECTED BY:	RSD

	REQUIRED	ACTUAL	ALP	CONFORM
TAXIWAY INVENTORY				
TAXIWAY WIDTH:	35'	40' & 50'		✓
TAXIWAY SAFETY AREA WIDTH:	79'	(12)		NO
TAXIWAY OBJECT FREE AREA WIDTH:	131'	(13)		NO
DIST. FROM CENTERLINE TO FIXED OR MOVEABLE OBJ.	65.5'	(13)		NO
PAVEMENT EDGE LIP HEIGHT (MIN AND MAX):	1.5" - 3"	FLUSH		NO
PAVEMENT MARKING TYPE:		YELLOW		✓
PAVEMENT MARKING CONDITION:		POOR		N/A
TAXIWAY LIGHTING INVENTORY		NONE		N/A
DISTANCE FROM PAVEMENT EDGE:	10'			
MAXIMUM DISTANCE BETWEEN LIGHTS:	200'			
TYPE:				
CONDITION:				
COLOR:	BLUE	▼		•

MISCELLANEOUS

TYPE OF BEACON: NONE

SIZE OF BEACON: N/A

OTHER LIGHTING AIDS (VASI,PAPI,REIL): NONE

WINDCONE (CONDITION & COMPLIANCE): NW CORNER OF 12 END APRON; GOOD COND; 20' HIGH

SEGMENTED CIRCLE (CONDITION & COMPLIANCE): NONE

WINDCONE (CONDITION & COMPLIANCE): NEAR MIDFIELD; GOOD COND BUT SOCK NEARLY GONE; 20' HIGH

SEGMENTED CIRCLE (CONDITION & COMPLIANCE): POOR - MISSING PANELS AND VERY WEATHERED

FENCING: FAIR TO GOOD; MIXTURE OF WOOD POST JACK AND METAL POST

SIGNS: (TYPE, CONDITION, PLACEMENT)

NONE

COMMENTS: (8) PINE TREES LEFT AND RIGHT OF CL (25%) AND BRUSH BEYOND FENCE (12%) PENETRATE APPROACH
SURFACE; (9) RISING TERRAIN IN RSA; (10) FENCE IN OFA; (11) TREES (10%), BRUSH (8%) AND TERRAIN PENETRATE
APPROACH SURFACE
(12) SHALLOW GRADING OF SHOULDERS SIMILIAR TO RUNWAY
(13) SUBSTANTIAL SAGE BRUSH IN OFA ON BOTH TAXIWAYS, TAXIWAY AT 30 END HAS 3' NONFRANGIBLE WOOD POST
WITH VEHICLE ALERT SIGN 33' FROM CL - IN TAXIWAY OFA